

- Block stains of substances likely to reappear with a coating of shellac.
- Sandpaper synthetic surfaces, painted surfaces, wood.
- Made a test coating on old paint.
- Clean and treat all traces of mould on the surface.
- Dilute Geckocoat with its thinner to a maximum of 10% of volume for absorbent surfaces.
- Apply Geckocoat with a brush.
- Protect well other surfaces from splashes of Geckocoat. If necessary immediately clean the splashes with water. There is irreversible danger of splashes sticking hard.

Tools: Brush

Color: One can tint Geckocoat with our pigments up to 5 % compared to the weight used, e.g. 80 gm of pigment per litre.. To add pigments, mix with a quantity of Geckocoat thinner to obtain a creamy paste without lumps and then incorporate product.. Use between 70 and 100ml of thinner for 80 G of pigment. If other pigments are used, it is necessary to check their resistance to the alkaline ones.

Temperature: The minimal temperature of application is 8°C.

Cleaning of the tools: Clean with water immediately after use.

Storage: If prevented from freezing, Geckocoat is preserved for 6 months minimum. It is important to close the containers well. When the container is part used, clean the walls with a little thinner and cover with a plastic film during breaks in order to protect from drying.

Precautions: Alkaline product irritating for the eyes, the skin and the mucous membranes. Protect the eyes and the skin with glasses and protective gloves. In the event of skin contact, wash abundantly with water. In the event eye contact, wash for several minutes with running water, by holding the eye open. Consult a doctor in the event of persistent pain. Do not throw remaining product in drains or rivers. Allow to dry and deposit the residues in a dry state with domestic waste.

NOTE: Dilute Geckocoat only with its thinner and never with silicate or water. Take into account the possible allergies to even natural ingredients! Keep out of reach of children.

To order or for further information and details about training courses contact:

Naturepaint Limited
The Old Dairy
Fonthill Bishop
Wiltshire SP3 5SH

[www. Naturepaint.com](http://www.Naturepaint.com)

Tel: 0845 36 70 140



GEKOCOAT OVERVIEW

Geckocoat Coating

Geckocoat is an ideal coating for restoration work because it adheres on almost all the types of surfaces. Geckocoat is an innovative mineral paint that has an incomparable capacity for adhesion. Composed of a binder containing silicate (silicon dioxide) with a mineral load, Geckocoat is white and granulous (0,5 mm fine, 1.0mm coarse).

The binder of Geckocoat has existed for hundred of years but for another use. It is one of the ingredients which is used in the manufacture of the wine and the grape juices to aid clarification.. The lizard gecko inspired the name of our product because under the legs of this animal, one finds several million small fine hairs making contact with surface. These millions of small points of contact allow him to stick on even smooth vertical surfaces. It is in the same principle that Geckocoat functions, by an enormous quantity of small points of contact with the surface.

Use

Geckocoat is adapted to be used as a priming coat but also for the finishing of walls and ceilings. It can, moreover, be covered with a layer of glaze to create varied decorative effects. Geckocoat can cover various types of surfaces and materials; natural or artificial. It is applicable on a large range of surfaces like several varieties of; wallpapers, wood, wood agglomerated, coatings, concrete, plates of gypsum, stones, old paintings, plastics, glasses, metals, ceramic tiles. A test application should be made on latex and concrete.

Properties

- Priming coat or of completion
- Granularity of 0,5mm or 1mm
- White on completion, slightly velvety and able to be also tinted
- Mineral composition
- Great capacity of covering
- Adhere on a great number of the types of surfaces
- Resists acids, alkaline and several solvents
- Do not support the growth of moisture thanks to its alkalinity
- Without organic or synthetic binder

Ingredients

Water, sodium silicates, silicon dioxide dissolved in water, dioxide titanium, talc, chalk, borax, xanthane, cellulose, mould preventive (< 0,1%)

Application

- The surface must be clean, dry, solid, be degreased and removed from any colouring substance likely to reappear.
- Wash old paint with Geckocoat binder adhesive, to eliminate the remains of chalky paintings or loose solids.
- Eliminate the remains of wallpaper adhesive and brush the surface carefully.
- Eliminate the friable, not very solid parts of the coatings,