



PUNIC WAX OVERVIEW

Punic Wax is a soap based on beeswax with a creamy consistency. The beeswax is molten, cleaned and then bleached over active charcoal and Fuller's earth using a special method. In a process developed by KREIDEZEIT the bleached wax is saponified with potash so that it is partly water soluble and easy to apply.

APPLICATION

Punic Wax is a matt or (after polishing) shiny wax coating for:

- Stuccolustro- and Tadelakt works,- Casein Shine Surfacer- Marble imitations (e.g. on marble floor paint)
- Encaustic- Casein paint coatings

As an addition to casein marble floor paint or glue-bound distemper for:

- Spattle techniques - Stencil paintings - Coatings to be polished

PROPERTIES

Creamy, paste-like, odorless, without organic solvents (the solvent is water), satin-finished to high-gloss after polishing and thus dirt-repelling, antistatic, diffusible.

INGREDIENTS

Beeswax (bleached free of chlorine and without residues), potash, water.

USAGE

(1) Stuccolustro works

Apply Punic Wax with a Venetian trowel (Art.No. KN4227/4228) or a Spring Steel trowel (Art.No. K N4225) in one or more thin layers. Polish with trowel after drying.

(2) Tadelakt works

Apply Punic Wax on the set and dry Tadelakt surface with a flexible plastic smooth-edged spattle or Japanese spatula in a thin layer. Can also be applied on soaped Tadelakt. Polish with soft cloth or bristle brush after drying.

(3) Marbling

Apply Punic Wax e.g. on Marble floor coatings with adequate marbling as described in (1) with a trowel. Polish after drying with the trowel or, for an evenly shine, by hand using soft cloths, horsehair-bristle or a polishing machine. (Attention: too high pressure or too high RPM can damage the surface because of heat.) The wax coating results in a deep and transparent surface, very similar to real marble.

(4) Wall coatings to be polished

Add 15% of Punic Wax to casein marble floor paint resp. glue-bound distemper (0.75kg of Punic Wax on 5kg of paint powder) to achieve a surface with a wonderful, satin-finished shine. Apply the Punic Wax after the swelling time of the paint. Polish after drying.

DRYING TIMES: Approx. 5-6hrs at 20°C for pure Punic Wax.

YIELD: Approx. 30ml per m².

PACKAGE SIZE: Art.No. KN197 800ml Please refer to the valid price list for product prices.

STORAGE: If stored cool, dry and above zero degrees centigrade, Punic Wax can be kept for over 1 year.

CLEANING OF TOOLS: Clean immediately after use with water, use soap if necessary.

HAZARD CATEGORY: Xi, irritant

SAFETY ADVICE: Punic Wax is alkaline. Avoid eye contact. Rinse with plenty of water (also under the eyelids) in case of eyecontact and seek medical treatment. **Keep out of reach of children!**

To order or for further information and details about training courses contact:

Naturepaint Limited
The Old Dairy
Fonthill Bishop
Wiltshire SP3 5SH

www.Naturepaint.com

Tel: 0845 36 70 140